

1/11






Fig 1

2/11



3/11




Fig 4




Fig 5

4/11




Fig 6




Fig 7

5/11






Fig 8

Fig 9

Fig 10




Fig 11

6/11




Fig 12




Fig 13

7/11




Fig 14




Fig 15

8/11




Fig 16




Fig 17

9/11




Fig 18




Fig 19

10/11




Fig 20




Fig 21





Fig 22

11/11

Surface  
measurement  
error



Probe deflection/  
Probe force

Fig 23